	Property is: Single Fa	mily [] Di	ıplex	☑ Other □		
Date:	3/23/2016						
take no respo		after the in	spectio	on date	e, or for omissions throu	e, the Redevelopment Authority, and their representatives igh error or oversight. The list does not necessarily includ ME programs.	е
Exterior (Condition Report						
Location Site	Required Work Landscaping	n/a _[、	∕] Ye:	s 🔲	Note/Comments Self Help	Cost \$	
	Steps/Handrails	n/a 🖸	✓ Ye	s 🗌		\$	
	Service walks	n/a	✓ Ye	s 🗌		\$	
	Fencing	n/a [/ Ye	s 🗌		\$	
	Parking	n/a [/ Ye	s 🗌		\$	
	Retaining walls	n/a [/ Ye	s 🗌		\$	
	Other	n/a] Ye	s 🗌		\$	
	Other	n/a [] Ye	s 🗌		\$	
Garage	Singles: repair	n/a] Ye	s 🗌		\$	
	Shingles: Roof over existing	n/a [] Ye	s 🗌		\$	
	Shingles:Tear off & re-roof	n/a [] Ye	s 🗌		\$	
	Gutters/downspouts	n/a [] Ye	s 🗌		\$	
	Flashing	n/a] Ye	s 🗌		\$	
	Eaves	n/a [] Ye	s 🗌		\$	
	Siding	n/a [] Ye	s 🗌		\$	
	Doors	n/a [] Ye	s 🗌		\$	
	Windows	n/a] Ye	s 🗌		\$	
	Slab	n/a [] Ye	s 🗌		\$	
	Paint	n/a [] Ye	s 🗌		\$	
	Electrical	n/a [] Ye	s 🗌		\$	
_	Other	n/a [] Ye	s 🗌		\$	
Porches	Roof	n/a [∕ Ye:	s 🗌		\$	
	Deck-upper	n/a [/ Ye	s 🔲		\$	
	Decklower	n/a [/ Ye	s 🔲		\$	
	Steps/handrails	n/a [/ Ye	s 🗌		\$	
	Ceiling	n/a [/_Ye	s		\$	
	Guardrails	n/a 🗔	✓ Ye	s 🗌		\$	
	Structural	n/a [/ Ye	s 🗌		\$	
	Paint	n/a] Ye	s 🗸		\$ 20	00.00
	Other	n/a ┌	ר Ye:	s \square		\$	

Scope of Work for Property Located at: 3071 North 21st Street

House

Chimney	n/a 🗸 Yes 🗌	\$
Shingles: repair	n/a ✓ Yes 🗌	\$
Shingles: Roof over existing	n/a 🗸 Yes 🗌	\$
Shingles:Tear off & re-roof	n/a ☐ Yes ☑	\$ 8,000.00
Gutters/downspouts	n/a ☐ Yes ☑	\$ 1,200.00
Flashing	n/a 🗸 Yes 🗌	\$
Eaves	n/a 🗸 Yes 🗌	\$
Siding	n/a ☐ Yes ☑	\$ 1,000.00
Storm Doors	n/a 🗸 Yes 🗌	\$
Prime ("main") Doors	n/a 🗸 Yes 🗌	\$
Storm Windows	n/a 🗸 Yes 🗌	\$
Prime ("main") Windows	n/a 🗸 Yes 🗌	\$
Paint	n/a 🗸 Yes 🗌	\$
Foundation	n/a Yes vest foundation wall	\$ 25,000.00
Electrical	n/a ☑ Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a Yes	\$

Exterior: Estimated Cost:* \$ 35,400.00

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	Unit: Entire unit (single family) Upper unit of duplex					Lower unit of duplex Other	✓		
Mechanical Heating	Required Work					Other			
	Repair/replace boiler	n/a	V	Yes		_		\$	
	Repair radiation	n/a	✓	Yes		_		\$	
	Repair/replace furnace	n/a		Yes	V	_		\$	3,300.00
	Repair ductwork	n/a		Yes	✓	_		\$	500.00
	Replace thermostat	n/a	V	Yes				\$	
	Repair/replace grilles	n/a	V	Yes				\$	
Electrical	Tune boiler/furn. insp ht exchange	n/a	V	Yes		_		\$	
Liectrical	Repair/replace receptacles	n/a		Yes	V	_		\$	500.00
	Repair/replace switches	n/a		Yes	V	_		\$	500.00
	Repair/replace fixtures	n/a		Yes	V	_		\$	1,000.00
	Install outlets and circuits	n/a		Yes	✓			\$	1,000.00
	Install outlets and circuits	n/a	V	Yes				\$	
	Install outlets and circuits	n/a	V	Yes				\$	
	Install outlets and circuits	n/a	V	Yes				\$	
	Upgrade service	n/a		Yes	V			\$	950.00
	Other	n/a		Yes				\$	
	Other	n/a		Yes				\$	
Plumbing	Repair/replace kitchen sink	n/a		Yes				\$	
	Repair/replace kitchen sink fauce	n/a		Yes				\$	
	Repair/replace tub	n/a		Yes				\$	
	Repair/replace tub faucet	n/a		Yes		_		\$	
	Repair/replace toilet	n/a		Yes				\$	
	Repair/replace lavatory	n/a		Yes		_		\$	
	Repair/replace lavatory faucet	n/a		Yes				\$	
	Repair/replace wash tub	n/a		Yes				\$	
	Repair/replace wash tub faucet	n/a		Yes				\$	
	Unclog piping:	n/a		Yes		_		\$	
	Repair drain/waste/vent piping	n/a		Yes	V			\$	1,000.00
	Repair water piping	n/a		Yes	V	_		\$	1,000.00
	Repair/replace water heater	n/a		Yes	V	_		\$	750.00
	Other	n/a		Yes	V	complete kitchen		\$	1,500.00

n/a Yes 🗸 complete bath

Other

2,500.00

\$

Windows								
	Replace broken glass	n/a	V	Yes			\$	
	Repair or replace sash	n/a	V	Yes			\$	
Doors								
	Repair or replace doors	n/a		Yes	✓		\$	1,000.00
	Repair or repl. locks/latches	n/a	V	Yes		Self Help	\$	
Walls/Ceiling	gs							
	Repair or repl. @ defective	n/a		Yes	✓		\$	1,000.00
Paint								
	Repair or repl. @ defective	n/a		Yes	V		\$	1,000.00
Fire Safety								
	Install smoke/CO alarm:bsmt.	n/a		Yes	~	Self Help	\$	50.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	V	Self Help	\$	50.00
	Install smoke/CO alarm: 2nd flr.	n/a	V	Yes		Self Help	\$	
Handrails						-		
	Repair/replace defective	n/a		Yes	V	Self Help	\$	100.00
Stairs			_				_	
Floors	Repair defective	n/a	✓	Yes		_	\$	
1 10013	Repair defective	n/a		Yes	V	throughout	\$	2,500.00
Other	Tropul dolocare	.,, \			v		Ψ	
		n/a		Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	

Interior Co	ondition Report Unit: Entire unit (single family)					Lower unit of duplex		
Mechanical Heating	Upper unit of duplex Required Work	V				Other		
· ·	Repair/replace boiler	n/a	V	Yes		_		\$
	Repair radiation	n/a	V	Yes				\$
	Repair/replace furnace	n/a		Yes	V			\$ 3,300.00
	Repair ductwork	n/a		Yes	~			\$ 500.00
	Replace thermostat	n/a	V	Yes				\$
	Repair/replace grilles	n/a	V	Yes		_		\$
Electrical	Tune boiler/furn. insp ht exchange	€n/a	V	Yes		_		\$
Liectrical	Repair/replace receptacles	n/a		Yes	✓			\$ 500.00
	Repair/replace switches	n/a		Yes	V			\$ 500.00
	Repair/replace fixtures	n/a		Yes	✓	_		\$ 1,000.00
	Install outlets and circuits	n/a		Yes	V			\$ 1,000.00
	Install outlets and circuits	n/a	V	Yes				\$
	Install outlets and circuits	n/a	V	Yes		_		\$
	Install outlets and circuits	n/a	V	Yes				\$
	Upgrade service	n/a		Yes	✓			\$ 950.00
	Other	n/a		Yes				\$
	Other	n/a		Yes				\$
Plumbing	Repair/replace kitchen sink	n/a		Yes		_		\$
	Repair/replace kitchen sink fauce	n/a		Yes				\$
	Repair/replace tub	n/a		Yes				\$
	Repair/replace tub faucet	n/a		Yes				\$
	Repair/replace toilet	n/a		Yes				\$
	Repair/replace lavatory	n/a		Yes				\$
	Repair/replace lavatory faucet	n/a		Yes				\$
	Repair/replace wash tub	n/a		Yes				\$
	Repair/replace wash tub faucet	n/a		Yes				\$
	Unclog piping:	n/a		Yes				\$
	Repair drain/waste/vent piping	n/a		Yes	V	_		\$ 1,000.00
	Repair water piping	n/a		Yes	V			\$ 1,000.00
	Repair/replace water heater	n/a		Yes	V	_		\$ 750.00
	Other	n/a		Yes	V	complete kitchen		\$ 1,500.00

n/a Yes complete bath

\$ 2,500.00

Other

Windows								
	Replace broken glass	n/a [√	Yes			\$	
	Repair or replace sash	n/a [√	Yes			\$	
Doors	Repair or replace doors	n/a [Yes	V	~	\$	1,000.00
	Repair or repl. locks/latches	n/a [√	Yes		Self Help	\$	
Walls/Ceiling	gs Repair or repl. @ defective	n/a [Yes	✓		\$	1,000.00
Paint	Repair or repl. @ defective	n/a [7	Yes			\$	1,000.00
Fire Safety					_			.,,
	Install smoke/CO alarm:bsmt.	n/a [√	Yes	Ш	Self Help	\$	
	Install smoke/CO alarm: 1st flr.	n/a [√	Yes		Self Help	\$	
	Install smoke/CO alarm: 2nd flr.	n/a [Yes	✓	Self Help	\$	50.00
Handrails	Repair/replace defective	n/a [Yes	✓	Self Help	\$	100.00
Stairs	Repair defective	n/a [√	Yes			\$	
Floors	Repair defective	n/a [Yes	V	throughout	\$	2,500.00
Other		n/a [Yes			\$	
		n/a _[Yes			\$	
		n/a [Yes			\$	
		n/a [Yes		-	\$	
						Interior: Estimated Cost:	\$	40,350.00
						Total Exterior and Interior Cost:*	\$	75,750.00
						*average contracted cost. Actual costs may vary. Self help will reduce	ce the amount.	
Inspected b	ov: Andy Yeager					Date: 3/23/16		

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.